

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/19/2019

Submitted Date:

11/19/2019

Document Number:

699300619

FIELD INSPECTION FORM

Loc ID 318173 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10633
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC
Address: 1801 CALIFORNIA STREET #2500
City: DENVER State: CO Zip: 80202

Findings:

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240774	WELL	PR	05/01/1976	GW	123-08562	MCCOY 1	SI

General Comment:

(This area is intentionally left blank for general comments.)

Location			
Lease Road:			
Type	Access		
comment:	well site is in the middle of an alfalfa field		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Weeds growing around WH are dead and now considered debris		
Corrective Action:	Comply with Rule 603.f		Date: 07/23/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Steel pipe		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 240774 Type: WELL API Number: 123-08562 Status: PR Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 11/19/2019 at approximately 1400 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Crestone peak Resources location:</p> <p style="text-align: right;">McCoy #1 at API #05- 123-08562 in Weld County Colorado.</p> <p>While there, I observed a SI wellsite. This is a follow up inspection per Doc. # 693500587 At time of inspection well appears not to have plunger lift and not producing. During this inspection the following possible compliance issue was observed and is now delinquent: 603.f housekeeping: Weeds growing around WH are now dead and considered debris. CA date 7/23/2019 See attached photos. Location is dry, weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	11/19/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402243902	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992803
699300620	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4992795