

# Inspection Photos

Operator: Enduring Resources  
Location/API #: 067-08398  
Date: 11-14-2019



Photo 1. View of the project area from the well pad entrance facing center.






Photo 2. View of musk thistle and Canada thistle infestation in the eastern project area facing northward.





Photo 3. View of the northern project area from the northeastern corner facing westward. Area is infested with musk thistles, with little desirable vegetation present.





Photo 4. View of reference area, comprised of sagebrush shrubland, with grasses planted in openings.