

Inspection Photos  
Operator: Williford Resources  
Location/API #: 067-06719  
Date: 11-19-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing in portions of the project area with mixed wheatgrasses, such as crested wheatgrass and western wheatgrass, as well as annual weeds such as cheatgrass and alyssum.





Photo 3. View of unused equipment within the southeastern project area.



Photo 4. View of reference area, comprised of open grass field.