

Inspection Photos
Operator: Williford Resources
Location/API #: 067-06624
Date: 11-19-2019



Photo 1. View of the project area from the northeastern corner facing center. Revegetation is progressing in portions, with grasses such as crested wheatgrass, but remains weedy in other portions with annual weeds such as yellow tumble mustard and alyssum.



Photo 2. View of unused pipe within the southeastern project area.



Photo 3. View of metal debris in the eastern project area.



Photo 4. View of reference area, comprised of sagebrush shrubland/grass field mosaic, with grasses (crested wheatgrass) and annual weeds in openings.