

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/20/2019

Submitted Date:

12/02/2019

Document Number:

699700062

FIELD INSPECTION FORM

Loc ID 316373 Inspector Name: Heil, John On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100264

Name of Operator: XTO ENERGY INC

Address: 110 W 7TH STREET

City: FORTH WORTH State: TX Zip: 76102

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Steiner, Natalie	9706754089	natalie_steiner@xtoenergy.com	Spills
Arauzo, Steven		steven.arauzo@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	
Dooling, Jessica		Jessica_Dooling@xtoenergy.com	Piceance Creek insp

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
270456	WELL	PR	09/01/2019	GW	103-10401	YELLOW CREEK FEDERAL 3-45-1	EI
468668	SPILL OR RELEASE	CL	11/14/2019		-	SPILL/RELEASE POINT	EI

General Comment:

On November 20, 2019, COGCC Environmental Staff (John Heil and Steven Arauzo) conducted an Environmental field inspection of XTO ENERGY INC (XTO Operator #100264) Location ID 316373 Yellow Creek Federal 3-45-1, Spill ID 468668 and Remediation Project 14580. Weather was cloudy and temperatures about 45 degrees Fahrenheit.

See previous inspections Doc# 699700036 (9/25/2019) and 699700046 (10/16/2019) for COGCC observations of Spill ID 468668 and Remediation Project 14580.

Inspected Facilities				
Facility ID: 270456	Type: WELL	API Number: 103-10401	Status: PR	Insp. Status: EI
Facility ID: 468668	Type: SPILL OR	API Number: -	Status: CL	Insp. Status: EI

Environmental**Spill/Remediation:**

Comment: COGCC staff observed a 90 feet by 115 feet by 25 feet deep excavation around the point of release (See photos). Two separate stockpiles of soil were present on location at time of inspection. The larger of the stockpiles measured approximately 60 feet by 75 feet by 15 feet tall and was mostly contained by a plastic berm. The smaller of the stockpiles measured approximately 45 feet by 30 feet by 10 feet tall.

Corrective Action: Operator shall properly treat or dispose of the stockpiled soil in accordance with Rule 907.f and provide that information on an eForm 27 under Remediation 14580.
Provide waste transportation and final disposition information in accordance with 907.b.(2) for all E&P waste transported off site.
Berms on the northeast side of the larger stockpile are in disrepair.

Date: 01/02/2020

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402251011	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5001479
699700067	20191120 photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5001478