

Inspection Photos

API: 05-043-06222

Operator: INCREMENTAL OIL & GAS (FLORENCE) LLC

Inspection Date: 12/4/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-043-06222 | Date: 12/4/2019

Inspection Photos



Photo 1. Facing northwest along the access road which appears to be driven on and not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06222 | Date: 12/4/2019

Inspection Photos



Photo 2. Vegetation is not established along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06222 | Date: 12/4/2019

Inspection Photos



Photo 3. Facing northwest toward the location. There are wattles displaced at the southeast side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06222 | Date: 12/4/2019

Inspection Photos



Photo 4. Facing west toward the southern portion of the location. A berm, small ditch, and wattles are installed around the southern perimeter. The concern is that the ditch is directed downhill which can accelerate stormwater and cause erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06222 | Date: 12/4/2019

Inspection Photos



Photo 5. Facing east. The small ditch and berm is directed down hill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06222 | Date: 12/4/2019

Inspection Photos



Photo 6. Facing north at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06222 | Date: 12/4/2019

Inspection Photos



Photo 7. Facing north at the west side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06222 | Date: 12/4/2019

Inspection Photos



Photo 8. Facing east toward the northern portion of the location. A berm and small ditch are installed around the southern perimeter. The concern is that the ditch is directed downhill which can accelerate stormwater and cause erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06222 | Date: 12/4/2019

Inspection Photos



Photo 9. Facing south toward the location. The soils are bare and not protected from wind erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06222 | Date: 12/4/2019

Inspection Photos



Photo 10. View of groundcover at the location. There is no vegetation establishing. It is uncertain if soils have been seeded. Seed soils should be and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06222 | Date: 12/4/2019

Inspection Photos



Photo 10. Facing east toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-043-06222 | Date: 12/4/2019