

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/09/2019

Submitted Date:

12/09/2019

Document Number:

696101668**FIELD INSPECTION FORM**Loc ID 302562 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		NBL_DJBU_Inspections@nblenergy.com	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299538	WELL	SI	09/01/2017	OW	123-29403	ROUSE USX A 05-05	SI

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Shut-In | SI.  
Battery: Inactive | Shut-down.

Centralized Battery serves 5 Location IDs (302563, 302562, 302564, 306456, 414025).  
(Well(s): 5: Shut-In | SI).

Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563  
for Battery / Facility, Equipment info.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

<b>Emergency Contact Number:</b>			
Comment:	Invalid Emergency number posted at wellsite. Refer to Rule 210.b. See photo #1.		
Corrective Action:	Post valid Emergency number at wellsite. Comply w/ Rule 210.b. See photo #1.		Date: 01/08/2020

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel		
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.519192,-104.582283	
Comment:	Centralized Battery serves 5 Location IDs (302563, 302562, 302564, 306456, 414025). Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.					
Corrective Action:					Date:	

**Paint**

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	299538	Type:	WELL	API Number:	123-29403	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: PRODUCTION RECORDS			
Comment:		<div>Shut-In   SI. COGCC records indicate last production: 07/2015. SI/TA well per variance Doc #401474555. (NOBLE). Yellow LTSI tags for SI/TA status present at wellsite. Locked-Out, Tagged Out   LOTO.</div>							
Corrective Action:							Date:		

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 12/09/2019 at approximately 14:37 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: NOBLE ENERGY INC  Location Name: ROUSE USX A-66N64W /5SWNW  Location ID: 302562  Well Name: Rouse USX A 05-05  API: 05-123-29403  Location County: Weld County, Colorado  Weather: Partly cloudy w/ partial snow coverage from prior storm.</p> <p>While there, I observed:</p> <p>Well(s): 1: Shut-In   SI.  Battery: Inactive   Shut-down.</p> <p>Centralized Battery serves 5 Location IDs (302563, 302562, 302564, 306456, 414025).  (Well(s): 5: Shut-In   SI).</p> <p>Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.</p> <p>During this inspection the following possible compliance issues were observed:  1.) Invalid Emergency number posted at wellsite. Refer to Rule 210.b.  Post valid Emergency number at wellsite. Comply w/ Rule 210.b.  Corrective Action date: 01/08/2020.  See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/09/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101669	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5009036">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5009036</a>