

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/03/2019

Submitted Date:

12/03/2019

Document Number:

687905839**FIELD INSPECTION FORM**Loc ID 325973 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**23 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215661	WELL	PR	06/19/1990	GW	067-07266	MF SHARP A 1	PR

General Comment:[Site inspection and equipment inventory with photo document at the end of this report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign posted at entrance to location.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Tank labels and placards posted as stickers on one tank. Sign on east tank and those which are on the ground are not legible or standing. See photo# 6,7,9,11.			
Corrective Action:	Install signs to comply with Rule 210.			Date: 01/03/2020
Emergency Contact Number:				
Comment:	Contact information posted on sign at entrance to location.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	WEEDS			
Comment:	Weeds, tumbleweeds and kochia along portions of western cattle panels and fired equipment separator. Also present inside and outside tank battery secondary containment as well as fired equipment heaters on heated tanks. See photo# 3,6,7,9.			
Corrective Action:	Remove weeds per Rule 603.f.			Date: 12/10/2019
Type	TRASH			
Comment:	Trash or unserviceable equipment located around wellhead. See photo #2.			
Corrective Action:	Remove trash per Rule 603.f.			Date: 12/10/2019
Type	UNUSED EQUIPMENT			
Comment:	SS tubing outside meter house, fuel cell and catalytic heater in meter house and pipe fittings are all unused equipment. See photo# 4,5,6			
Corrective Action:	Remove unused equipment per Rule 603.f.			Date: 12/18/2019
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	TANK BATTERY			
Comment:	Cattle panels around tank battery.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Cattle panels around wellhead and pumpjack.			

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle panels around separator and meter house.		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:	(1) On separator stack. (2) On heated tanks.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Metal building with produced water electric transfer pump equipment and MCC.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric VFD motor with MCC installed on pumping unit.		
Corrective Action:		Date:	
Type: Flow Line	# 7		
Comment:	1-3" flowline from wellhead to separator. 1-1" flowline from separator to heated tank fuel gas. 1-2" flowline from separator dump valve to produced water tanks. 1-3" flowline from separator to meter house. 1-4" flowline from meter house to offsite dogleg. 1-2" flowline from produced water tanks to water transfer pump. 1-2" flowline from water transfer pump to offsite gathering system.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead has approx. a 5' diameter area of stained soil/gravel around it. Note that rod oiler is missing lid as pieces are laying on the ground below. See photo#2		
Corrective Action:	Remove and properly dispose stained soil/gravel per Rule 1002.f.(2).	Date:	12/10/2019

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
----------	---	----------	------	---------	--------

PRODUCED WATER	1	<50 BBLS	PBV STEEL		,	
Comment: 21 BBL tank.						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment: Secondary containment berm has deteriorated and been compromised from wildlife burrows around inside and outside portions of containment and from lack of maintenance. See photo# 6,7,8,9,10,11.				
Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).				
Date: 12/23/2019				

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		
Date:		

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities									
Facility ID:	215661	Type:	WELL	API Number:	067-07266	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Ditches	Pass	Ditches	Pass			
Berms	Pass	Compaction	Pass			
Compaction	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402252859	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003349
687905840	MF Sharp A1 inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003321