

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/03/2019

Submitted Date:

12/03/2019

Document Number:

687905844

FIELD INSPECTION FORM

Loc ID 312063 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

23 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections
Labowskie, Steve		steve.labowskie@state.co.us	COGCC

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259759	WELL	PR	03/15/2002	GW	067-08423	HUNGERFORD A 2	PR
298810	WELL	PR	07/11/2010	GW	067-09633	HUNGERFORD A 4	PR

General Comment:

[Site inspection and equipment inventory with photos at the end of this report.](#)

Location			
Lease Road:			
Type	Access		
comment:	Maintained gravel access road.		
Corrective Action			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Labels and placards posted on tank.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information posted on signs.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment spool pieces sitting on the ground next to the separator.		
Corrective Action:	Remove unused equipment per Rule 603.f.		Date: 12/18/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Cattle panels around separator and MCC.		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Cattle panels around tank.		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 2		corrective date
Comment:	Wellheads with block valve assemblies installed.		

Corrective Action:		Date:	
Type: Flow Line	# 10		
Comment:	2-4" flowlines from wellheads to dual separator. 2-2" flowlines from dual separator blowdown to produced water tank. 2-2" flowlines from dual separator dump valves to produced water tank. 2-4" flowlines from dual separator merging to 1-4" flowline to offsite dogleg. 1-2" flowline from produced water tank transfer pump to offsite gathering system.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On produced water tank vent stack.		
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:	Inside dual separator building.		
Corrective Action:		Date:	
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 2		
Comment:	Electric VFD motors with MCC on both pumping units.		
Corrective Action:		Date:	
Type: Vertical Separator	# 2		
Comment:	Dual separator unit.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		
Comment:	95 BBL tank with electric driven transfer pump and level control equipment installed.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Double-wall tank with level control equipment installed.			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 259759 Type: WELL API Number: 067-08423 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Facility ID: 298810 Type: WELL API Number: 067-09633 Status: PR Insp. Status: PR

Producing Well

Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Culverts	Pass			
Berms	Pass	Berms	Pass			
Gradient Terraces	Pass	Gravel	Pass			
Gravel	Pass	Ditches	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402252861	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003350
687905845	Overview photo looking south.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003324
687905846	Unused equipment next to separator.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5003325