

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/03/2019

Submitted Date:

12/03/2019

Document Number:

693501854

FIELD INSPECTION FORM

Loc ID 320512 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 8 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:


Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	All inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
272278	WELL	SI	09/01/2019	OW	001-09508	MORRISON 9-1	SI

General Comment:

Location			
Lease Road:			
Type	Access		
comment:	Access road has deep ruts and is in disrepair. will need to be repaired when conditions allow.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Well head sign is on site but in disrepair. Well need to replace sign in near future. See Photo 1		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil under rig		
Corrective Action:	Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 907A.		Date: <u>12/17/2019</u>
Type	OTHER		
Comment:	Stained soil around well head		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: <u>12/17/2019</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	YES		
Comment:	At time of inspection crew was venting gas out the well head to blow down well to perform work.		
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:



Inspected Facilities

Facility ID: 272278 Type: WELL API Number: 001-09508 Status: SI Insp. Status: SI

Workover

Comment: KPK rig performing well meaintenance.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday December 3, 2019 at approximately 11:00AM, I, Inspector Randy Silver, conducted an on-site inspection. Location: Morrison #9-1 Operator: KP Kauffman API#: 05-001-09508 County: While there, I observed Work over rig on well site During this inspection the following possible compliance issues were observed: Stained soil: Rule 907A Corrective action date of 12-17-19 see photo 3 Stained soil: Rule 907e Corrective action date of 12-17-19 See photo 4 This is a follow up inspection per Doc#693501615. At time of inspection corrective actions appear to be addressed. At time of inspection I observed what appeared to be crew venting gas out the backside of the well head with rig running to relieve pressure to work on well. I spoke with KPK rig supervisor Rick Ramos if this was the safest way to perform the work he stated no, crew should have topped killed well with water. Crew immediately closed well and proceeded to top kill well. Weather conditions: Clear and location is muddy and has snow. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	12/03/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402252363	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5002922
693501855	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5002916