

Inspection Photos
Operator: Williford Resources
Location/API #: 067-06771
Date: 11-19-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Vegetation is largely comprised of smooth brome.



Photo 3. View of stained soils, approximately two feet long and wide at the well pump jack.



Photo 4. View of the northern project area from the northeastern corner facing westward. Piles of what appears to be hydrocarbon-impacted material stored within the northwestern project area.



Photos 5/6. View of soil material that appears to be impacted by hydrocarbon waste, stored within the northwestern project area.



Photo 7. View of reference area, largely comprised of smooth brome, and scattered sagebrush plants.