

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2019

Submitted Date:

12/05/2019

Document Number:

693200461

FIELD INSPECTION FORMLoc ID 314343 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL & GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Whittington, Ellice		ellice.whittington@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
228463	WELL	SI	02/01/2017	OW	103-05320	TRANCO 5A	SI

General Comment:

Engineering Integrity Inspection performed on December 4, 2019.

ALL CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Photo log attached

Inspected Facilities

Facility ID: 228463 Type: WELL API Number: 103-05320 Status: SI Insp. Status: SI

Flowline

#1	Type: Non-Well Site	2 of Lines
----	---------------------	------------

Flowline Description

Flowline Type: Non-Well Site Size: 2" Material: Carbon Steel
 Variance: No Age: 10-15 Yrs Contents: Other

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: The off location flowline runs from the wellhead to facility/ battery. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.

Note: Operator has not registered any off location flowlines with COGCC; Corrective Action outlined may be applicable to additional wells operated by Lasso Oil & Gas

Corrective Action: Operator shall comply with the following COGCC rule:

1101.a. Off-Location Flowline Registration.

(1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off-location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402255697	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5006203
693200462	Lasso	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5006198