

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/10/2019

Submitted Date:

12/12/2019

Document Number:

690101575

FIELD INSPECTION FORM

Loc ID 307121 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 95233
Name of Operator: WELLINGTON OPERATING COMPANY
Address: 6065 S QUEBEC ST STE 200
City: CENTENNIAL State: CO Zip: 80111

Findings:

- 2 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Pomeroy, Bradley		pomoco@msn.com	
Gracey, Cameron		graceyservices@msn.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Peterson, Tom		tom.peterson@state.co.us	
Whittington, Ellice		ellice.whittington@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216911	WELL	PR	08/01/2008	OW	069-06098	WELLINGTON MUDDY UNIT 5-3	EG

General Comment:

COGCC Flowline Inspection Only. Photos Uploaded.
The Corrective Actions identified during this COGCC (EG) field inspection are located in the flowline section of report.
ALL CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Inspected Facilities

Facility ID: 216911 Type: WELL API Number: 069-06098 Status: PR Insp. Status: EG

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment:

This well is currently producing.
 The off location flowline (wellhead line) runs south from location. The Muddy Unit North Battery is located approximately 1.5 Miles south of the wellpad. The off location flowline (s) have not been registered with COGCC; Operator has not submitted COGCC Form 44.
 Note: Operator has not registered any off location flowlines with COGCC; The Corrective Action outlined is applicable to all wells operated by Wellington Operating Co with off location flowlines. Additional inspections may be forthcoming.

Corrective Action:

Comply with the following COGCC rule:
 1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101578	Signage at wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5011437
690101579	Pump Jack	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5011438
690101580	View south from wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5011439