

Inspection Photos  
Operator: BP America  
Location/API #: 067-09886  
Date: 12-10-2019



Photo 1. View of the project area from the southwestern corner facing center.





Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing in portions of the reclamation area with grasses such as sand dropseed. However, a significant portion of the interim reclamation area is vegetated with the noxious weed jointed goatgrass.





Photo 3. View of musk thistles within the northern project area. Approximately 50 individuals observed.





Photo 4. Closeup view of jointed goatgrass plants in foreground and densely populated in background. Photo taken on the southern fill slope.





Photo 5. View of reference area in background, comprised of irrigated grass field. Residential housing present north and east of the well pad.