

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/12/2019

Submitted Date:

12/12/2019

Document Number:

687905909**FIELD INSPECTION FORM**Loc ID 428309 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 1199 MAIN AVENUE SUITE 101City: DURANGO State: CO Zip: 81301**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:20 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428302	WELL	PR	01/16/2017	LO	067-09886	ANDERSON C 2	PR
428317	WELL	PR	01/16/2017	LO	067-09887	ANDERSON C 3	PR

General Comment:

Site inspection and equipment inventory with photos at the end of this report.

Location			
Lease Road:			
Type	Access		
comment:	Gravel access road.		
Corrective Action	L	Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Labels, volume, NFPA missing from produced water tank. NFPA and labeling missing from chemical injection container/tank on C3 well.		
Corrective Action:	Install signs/labels to comply with Rule 210.d.		Date: 01/12/2020
Type	WELLHEAD		
Comment:	Signs posted at entrance to location.		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	Contact information posted on sign at entrance.		
Corrective Action:		Date:	
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil and gravel approx 4' in diameter around C3 wellhead.		
Corrective Action:	Clean up and dispose of stained soil/gravel per Rule 1002.f(2).		Date: 12/18/2019
Type	WEEDS		
Comment:	Dead weeds within 25' around fired separator and combustible equipment.		
Corrective Action:	Remove weeds per Rule 603.f.		Date: 12/19/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: <input type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Flow Line	# 12		corrective date
Comment:	2-3" flowlines from wellheads to separators. 2-2" flowlines from separator blowdowns to produced water tank. 2-2" flowlines from separator dump valves to produced water tank. 2-2" flowlines from separator dump valves to offsite produced water gathering system. 2-3" flowlines from separators to meter houses. 2-4" flowlines from meter houses to offsite dogleg.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	C3 well with electric VFD motor and MCC installed on pumping unit.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		

Comment:	Installed on C3 wellhead only.		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 3			
Comment:	(2) On separator stacks (1) On produced water tank vent stack.		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 2			
Comment:	PVC bradenhead access.		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 2			
Comment:	Wellheads with block valve assemblies installed.		Date:	
Corrective Action:			Date:	
Type: Vertical Heated Separator	# 2			
Comment:			Date:	
Corrective Action:			Date:	
Type: Gas Meter Run	# 2			
Comment:			Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLs	PBV STEEL		,
Comment:	95 bbl tank. See labels/placards section for CA information. Static grounding cable installed on tank.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected FacilitiesFacility ID: 428302 Type: WELL API Number: 067-09886 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 428317 Type: WELL API Number: 067-09887 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gradient Terraces	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			
Ditches	Pass	Ditches	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for chemical injection.
Gravel	Pass					
Compaction	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905910	Overview photo looking East.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5012285
687905911	Missing tank label/placard.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5012286
687905912	Missing container label/placard.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5012287
687905913	Stained soil around C3 wellhead.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5012288
687905914	Weeds around fired equipment.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5012289