

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/04/2019

Submitted Date:

12/06/2019

Document Number:

690101561**FIELD INSPECTION FORM**Loc ID 333155 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 51760Name of Operator: LUNDVALL OIL & GAS INCAddress: P O BOX 632City: GREELEY State: CO Zip: 80632**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Whittington, Ellice		ellice.whittington@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		dinosaurmike@comcast.net	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
245208	WELL	SI	11/01/2017	OW	123-13003	LUNDVALL 18	EG

**General Comment:**

COGCC Flowline Inspection Only. Photos Uploaded.

The Corrective Actions identified during this COGCC (EG) field inspection are located in the flowline section of report.

Note: The corrective actions required outlined on COGCC FIR Doc #679601638 submitted on 09/24/2019 are still applicable.

**ALL CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Inspected Facilities**Facility ID: 245208 Type: WELL API Number: 123-13003 Status: SI Insp. Status: EG**Flowline**

#1	Type:Non-Well Site	of Lines	
----	--------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:  
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: This well is currently shut in.

The off location flowline(s) (wellhead line) runs approximately 840' north-northwest from the wellhead to facility/ battery. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44.

Note: Operator has not registered any off location flowlines with COGCC; The Corrective Action outlined is applicable to all wells operated by Lundvall Oil and Gas with off location flowlines.

Corrective Action: Operator shall comply with the following COGCC rule:

1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.

Date: 10/31/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402256982	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007406">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007406</a>
690101567	Signage at tank battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007404">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007404</a>
690101568	View N from wellhead to facility/ battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007405">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5007405</a>