

Inspection Photos
Operator: BP America
Location/API #: 067-07916
Date: 12-10-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is in a dormant vegetative condition, and appears to be progressing similar to surrounding crop field.



Photos 3/4. View of unused equipment stored in the project area.



Photo 4. View of reference area, comprised of irrigated crop field.