

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-08215**  
**Date: 12-10-2019**



Photo 1. View of the project area from the western corner facing center.



Photo 2. View of erosional rilling within the southwestern project area.



Photo 3. View of the southwestern fill slope from the southern corner facing northwestward. Revegetation appears to be progressing, in a dormant and grazed condition with grasses such as western wheat grass and sand dropseed.



Photo 4. View of reference area, comprised of irrigated crop field.