

## Inspection Photos

Location Name: Jones-67S94W 17 SENW Pad & 17F Spills

Location ID: #335023 & Spill/Release IDs: #467054 & #469248

Inspection Date: November 25, 2019



**Photo #1 – Wellhead fence is damaged.**



**Photo #2 – View of tank battery from northwest corner.**



## Inspection Photos

Location Name: Jones-67S94W 17 SENW Pad & 17F Spills

Location ID: #335023 & Spill/Release IDs: #467054 & #469248

Inspection Date: November 25, 2019



**Photo #3 – Gravel base has been removed from southwest corner of tank battery in response to Spill/Release ID #467054.**



**Photo #4 – Patched area of tank battery liner had an apparent gap during inspection. Operator was notified of issue via phone on 11/26/2019.**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Jones-67S94W 17 SENW Pad & 17F Spills

Location ID: #335023 & Spill/Release IDs: #467054 & #469248

Inspection Date: November 25, 2019



**Photo #5 – Unused equipment and junk stored inside of south end of tank battery secondary containment area.**



**Photo #6 – Unused equipment stored inside of secondary containment area on east side.**



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



## Inspection Photos

Location Name: Jones-67S94W 17 SENW Pad & 17F Spills

Location ID: #335023 & Spill/Release IDs: #467054 & #469248

Inspection Date: November 25, 2019



**Photo #7 – Unused equipment stored inside of secondary containment area on west side.**



**Photo #8 – Overview of fenced separator area and flow path for fluids released by Spill/Release ID #469248, from north.**





## Inspection Photos

Location Name: Jones-67S94W 17 SENW Pad & 17F Spills

Location ID: #335023 & Spill/Release IDs: #467054 & #469248

Inspection Date: November 25, 2019



Photo #9 – View into flowline excavation, from east side.



Photo #10 – View of fenced flow path area from south side of flowline excavation.



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources



## Inspection Photos

Location Name: Jones-67S94W 17 SENW Pad & 17F Spills

Location ID: #335023 & Spill/Release IDs: #467054 & #469248

Inspection Date: November 25, 2019



**Photo #11 – Capped, unmarked 1" flowline riser located east of separators.**



**Photo #12 – Unidentified fluids observed in threads and rust-stained gravel beneath ball valve attached to tank in NE corner of containment area (1).**

**Note bull plug was not installed during inspection.**



## Inspection Photos

Location Name: Jones-67S94W 17 SENW Pad & 17F Spills

Location ID: #335023 & Spill/Release IDs: #467054 & #469248

Inspection Date: November 25, 2019



**Photo #13 - Unidentified fluids observed in threads and rust-stained gravel beneath ball valve attached to tank in NE corner of containment area (2).**

**Note bull plug was not installed during inspection.**