

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/09/2019

Submitted Date:

12/09/2019

Document Number:

696101670**FIELD INSPECTION FORM**Loc ID 306456 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288952	WELL	SI	08/01/2015	GW	123-24697	ROUSE-USX A 5-19	SI

General Comment:

This is a WELL inspection.
Well(s): 1: Shut-In | SI.
Battery: Inactive | Shut-down.

Centralized Battery serves 5 Location IDs (302563, 302562, 302564, 306456, 414025).
(Well(s): 5: Shut-In | SI).

Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563
for Battery / Facility, Equipment info.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type			
Comment:	Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	Invalid Emergency number posted at wellsite. Refer to Rule 210.b. See photo #1.	
Corrective Action:	Post valid Emergency number at wellsite. Comply w/ Rule 210.b. See photo #1.	Date: 01/08/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:	Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.519192,-104.582283	
Comment:	Centralized Battery serves 5 Location IDs (302563, 302562, 302564, 306456, 414025). Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	288952	Type:	WELL	API Number:	123-24697	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose:		<input checked="" type="checkbox"/> Shut In		<input type="checkbox"/> Temporarily Abandoned		Reminder: PRODUCTION RECORDS			
Comment:		<div>Shut-In SI. COGCC records indicate last production: 07/2015. SI/TA well per variance Doc #401474555. (NOBLE). Yellow LTSI tags for SI/TA status present at wellsite. Locked-Out, Tagged Out LOTO.</div>							
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 12/09/2019 at approximately 14:33 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: ROUSE-USX A-66N64W /5NWNW Location ID: 306456 Well Name: Rouse-USX A 5-19 API: 05-123-24697 Location County: Weld County, Colorado Weather: Partly cloudy w/ partial snow coverage from prior storm.</p> <p>While there, I observed: Well(s): 1: Shut-In SI. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 5 Location IDs (302563, 302562, 302564, 306456, 414025). (Well(s): 5: Shut-In SI).</p> <p>Refer to Field Inspection Report doc. #696101666 and/or Location ID #302563 for Battery / Facility, Equipment info.</p> <p>During this inspection the following possible compliance issues were observed: 1.) Invalid Emergency number posted at wellsite. Refer to Rule 210.b. Post valid Emergency number at wellsite. Comply w/ Rule 210.b. Corrective Action date: 01/08/2020. See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/09/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402258694	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5009053
696101671	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5009051