

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-09564
Date: 12-13-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing, largely with rubber rabbitbrush.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area, comprised of greasewood, snakeweed, and sand dropseed.