

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	At time of inspection wellhead sign is legible but faded. No corrective action at this time but sign will need addressed soon.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead weeds around PU base and electric panel area.		
Corrective Action:	Comply with Rule 603.f		Date: 11/25/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment # 1			corrective date
Comment:	Electric panel, transformers and meter box		
Corrective Action:			Date:
Type: Prime Mover # 1			
Comment:	electric motor		
Corrective Action:			Date:
Type: Pump Jack #			
Comment:			
Corrective Action:			Date:
Type: Bradenhead # 1			
Comment:	Partially exposed at surface		
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241724 Type: WELL API Number: 123-09513 Status: PR Insp. Status: PR

Producing Well

Comment:	PR	
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 12/10/2019 at approximately 1520 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Josephine B. Miles #3 at API #05-123-09513 in Weld County Colorado. While there, I observed a producing wellsite. This is a follow up inspection per Doc. # 699300589 During this inspection the following possible compliance issue was observed and is now delinquent: 603.f Housekeeping: Debris/ dead weeds around PU and Electric panel, transformer area. CA Date 11/25/2019 See attached photos #2, 3, 4 and 5. Location is wet and muddy, weather is partly cloudy. This inspection is being submitted to enforcement due to non compliance of COGCC Rules. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	12/10/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402259837	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5010125
699300719	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5010115