

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2019

Submitted Date:

12/11/2019

Document Number:

696101691

**FIELD INSPECTION FORM**Loc ID 332695 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
,		dnr_cogccengineering@state.co.us	
James, Brian		bjames@hpres.com	All Inspections
Brown, Tim		tbrown@hpres.com	MIT

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
271458	WELL	SI	05/01/2019	GW	123-22063	VAN WYKE 21-32	TA
293393	WELL	SI	09/01/2019	GW	123-26542	VAN WYKE 4-2-32	TA

**General Comment:**

This is a WELL inspection.

Well(s): 2: Temporarily Abandoned | TA.

Battery: Shut-down | Inactive.

Centralized Battery serves 2 Location IDs (332695, 332268).

(Well(s): 3: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696101444 and/or Location ID #332695  
for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696101444 dated 10/21/2019.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type				
Comment:	Refer to Field Inspection Report doc. #696101444 and/or Location ID #332695 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	2: wellsites.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	<p>Prior insp: Emergency number NOT posted at Van Wyke 21-32 wellsite. Refer to Rule 210.b. (30 Days). Post Emergency number at Van Wyke 21-32 wellsite. Comply w/ Rule 210.b. Corrective Action date: 11/21/2019.</p> <p>This insp: * Emergency number NOW posted at Van Wyke 21-32 wellsite. See photos #1, 2.</p>			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	2 wellsites: Iron panel			
Corrective Action:				Date:
<b>Equipment:</b>				
Type: Bradenhead	# 2			corrective date
Comment:	2 wellsites: Appears plumbed to surface.			
Corrective Action:				Date:
Type: Plunger Lift	# 2			
Comment:				
Corrective Action:				Date:
Type:	#			

Comment:	Refer to Field Inspection Report doc. #696101444 and/or Location ID #332695 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.362840,-104.463810	
Comment:	Centralized Battery serves 2 Location IDs (332695, 332268). Refer to Field Inspection Report doc. #696101444 and/or Location ID #332695 for Battery / Facility, Equipment info.					
Corrective Action:						Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 271458 Type: WELL API Number: 123-22063 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Form 5A doc #400987502 indicates TA w/ bridge plug. Date: 12/17/2015.  
Delinquent MIT: Van Wyke 21-32.  
No Current MIT on record. Refer to Rule 319.b.

Corrective Action: Delinquent MIT: Van Wyke 21-32.  
No Current MIT on record. Refer to Rule 319.b.

Date: \_\_\_\_\_

Facility ID: 293393 Type: WELL API Number: 123-26542 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.  
Form 5A doc #400987446 indicates TA w/ bridge plug. Date: 12/17/2015.  
Delinquent MIT: Van Wyke 4-2-32.  
No Current MIT on record. Refer to Rule 319.b.  
Refer to WARNING Letter Doc #402070112 dated 06/11/2019.  
Corrective Action Date: 09/30/2019. (WARNING Letter).

Corrective Action: No Current MIT on record. Refer to Rule 319.b.  
Refer to WARNING Letter Doc #402070112 dated 06/11/2019.  
Corrective Action Date: 09/30/2019. (WARNING Letter).

Date: 09/30/2019

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date:

**Pits:** ☐ NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 12/10/2019 at approximately 14:19 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: HIGHPOINT OPERATING CORPORATION  Location Name: VAN WYKE /4-2-32  Location ID: 332695  Well Names: Van Wyke 21-32, Van Wyke 4-2-32  API: 05-123-22063, 05-123-26542  Location County: Weld County, Colorado  Weather: Partly cloudy w/ partial snow coverage from prior storm.</p> <p>While there, I observed:  Well(s): 2: Temporarily Abandoned   TA.  Battery: Shut-down   Inactive.</p> <p>Centralized Battery serves 2 Location IDs (332695, 332268).  (Well(s): 3: Temporarily Abandoned   TA).</p> <p>Refer to Field Inspection Report doc. #696101444 and/or Location ID #332695 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696101444 dated 10/21/2019.  During this inspection, the following prior possible compliance issues appear to be addressed:  1.) Emergency number NOT posted at Van Wyke 21-32 wellsite.  Refer to Rule 210.b. (30 Days).  Post Emergency number at Van Wyke 21-32 wellsite.  Comply w/ Rule 210.b.  Corrective Action date: 11/21/2019.  * Emergency number NOW posted at Van Wyke 21-32 wellsite.  See photos #1, 2.</p> <p>During this inspection, the following prior possible compliance issues appear to be NOT addressed:  1.) Delinquent MIT: Van Wyke 21-32.  Form 5A doc #400987502 indicates TA w/ bridge plug. Date: 12/17/2015.  No Current MIT on record. Refer to Rule 319.b.</p> <p>2.) Delinquent MIT: Van Wyke 4-2-32  Form 5A doc #400987446 indicates TA w/ bridge plug. Date: 12/17/2015.  No Current MIT on record. Refer to Rule 319.b.  Refer to WARNING Letter Doc #402070112 dated 06/11/2019.  Corrective Action Date: 09/30/2019. (WARNING Letter).</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/11/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402260381	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5010720">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5010720</a>
696101692	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5010711">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5010711</a>