

## Inspection Photos Location #420972



location



location

## Inspection Photos Location #420972



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos Location #420972



**Thief hatch not secured**



**Pipe is open to atmosphere**



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos Location #420972



Piping on edge of location



Fencing not installed



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos Location #420972



Fencing not installed



Fencing not installed

