

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2019

Submitted Date:

12/18/2019

Document Number:

694900967

FIELD INSPECTION FORM

 Loc ID 420972 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 96850
 Name of Operator: TEP ROCKY MOUNTAIN LLC
 Address: PO BOX 370
 City: PARACHUTE State: CO Zip: 81635
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 20 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420971	WELL	PR	07/10/2012	OG	045-20263	CDOW KP 431-22	PR
420977	WELL	PR	10/04/2012	GW	045-20265	CDOW KP 511-22	PR
420978	WELL	PR	07/11/2012	GW	045-20266	CDOW KP 332-22	PR
420982	WELL	PR	10/04/2012	GW	045-20268	CDOW KP 322-22	PR
420983	WELL	PR	04/23/2013	GW	045-20269	CDOW KP 321-22	PR
420988	WELL	PR	10/04/2012	GW	045-20271	CDOW KP 441-22	PR
420990	WELL	PR	08/20/2012	GW	045-20272	CDOW KP 23-22	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 12/18/19 at approximately 2:00 PM, I, Inspector Scott Ramsey, conducted a routine inspection at TEP KP 22-22, at Location # 420972 in Garfield County, Colorado.

During this inspection the following possible compliance issues were observed:

- Debris around location/ fencing on west side of tanks
 - Tank at well heads is missing information, thief hatch is open, pipe on top of tank is open to atmosphere.
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	tank at well heads is missing information		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	01/20/2020
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	
Good Housekeeping:			
Type	DEBRIS		
Comment:	piping and fencing on west side of location		
Corrective Action:	Comply with Rule 603.f .	Date:	12/27/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	hog panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	hog panel not complete		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	chemical tank		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	1	OTHER	STEEL AST		,	
Comment:	not sure of capacity, thief hatch is unlatched and 2 inch pipe on top of tank is open to atmosphere. Tank is next to well heads hooked to braden heads.					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	HEATED STEEL AST		,	
Comment:	centralized containment with produced water tanks					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	5	300 BBLs	HEATED STEEL AST		,	
Comment:	centralized containment with condensate tanks Two (2) tanks are not heated					
Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	420971	Type:	WELL	API Number:	045-20263	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420977	Type:	WELL	API Number:	045-20265	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420978	Type:	WELL	API Number:	045-20266	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420982	Type:	WELL	API Number:	045-20268	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420983	Type:	WELL	API Number:	045-20269	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420988	Type:	WELL	API Number:	045-20271	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	420990	Type:	WELL	API Number:	045-20272	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Tank at well heads is missing information, thief hatch is open, pipe on top of tank is open to atmosphere and there is no containment. Refer to photograph of observed compliance issue. Debris around location/ fencing on west side of tanks	ramseys	12/18/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900968	694900967	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017166