

Inspection Photos

Operator: Hilcorp Energy
Location/API #: 067-08148
Date: 12-18-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Location is partially snow covered at this time. Revegetation is in a dormant vegetative condition, and largely comprised of intermediate wheatgrass.



Photo 3. View of musk thistles in a post-flowering condition within the interim reclamation area.



Photo 4. View of reference area, comprised of a grass field in dormant vegetative condition.