

Inspection Photos  
Operator: Enduring Resources  
Location/API #: 067-08391  
Date: 12-18-2019



Photo 1. View of the project area from the western edge of the working area facing center.



Photo 2. View of the northern fill slope from the northeastern corner facing westward. Tall vegetation is comprised of weeds such as kochia and Russian thistle. Smooth brome observed beneath weeds. Weeds need to be managed to encourage desirable vegetation.





Photo 3. View of weed debris within the project area.



Photo 4. View of reference area comprised of irrigation grass field that is largely snow covered at this time.