

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused flow line risers have been marked		
Corrective Action:	Comply with Rule 603.f For unused, unmarked flow line risers 24 hrs. to lock out tag out. 30 days to remove riser.	Date:	09/30/2019

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	steel pipe		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Electrical transformers, breaker panel and meter. Barb wire		
Corrective Action:		Date:	

Equipment:

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Electrical transformers, breaker panel and meter.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares containmnet with crude oil tank			
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities

Facility ID: 240242 Type: WELL API Number: 123-08030 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Monday 12/16/19 at approximately 11:00 am, I, Inspector Robbie Revas, conducted an on-site inspection at The Mahoney-Perrin #1 KP Kauffman location at API #05-123-08030 in Weld County Colorado. While there, I observed a Shut in well and tank battery. This is a follow up inspection per Doc. # 699300059 During this inspection the following compliance issues appear to have addressed: 907.e Stained soil around WH appears to have been removed See photos #2 & 4. 907.e Stained soil a PJ base appear to have been removed See photo #5. 603.f Weeds growing on location appear to have been removed See photo # 3 907.e Stained soil in Compressor shed appears to have been removed see photo #12 605.d Mechanical issue: hammer union with possible leak appears to have been tightened. See photo 13 603.f Trash: Unused material corrugated tin on location appears to have been removed see photo 10 603.fTrash: unused material in compressor shed appears to have been removed. See photo # 12 During this inspection the following compliance issues appear to have been partially addressed and is delinquent: Unmarked flow line risers:Risers have been marked but not LOTO or removed Rule 603.f 24 hrs. to LOTO 30 days to remove riser CA date 9/30/2019. See photos 7 & 8. Location is dry and weather is clear. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary Inspection. This is a summary of inspection report.</p>	revasr	12/16/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402264611	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5014646
699300745	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5014640