

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/22/2019

Submitted Date:

12/23/2019

Document Number:

688306575

FIELD INSPECTION FORM

Loc ID 317137 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10330
Name of Operator: INVESTMENT EQUIPMENT LLC
Address: 412 W PLATTE AVE
City: FT MORGAN State: CO Zip: 80701

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	COGCC EPS
Chisholm, Jim	405-642-9437	investmentequipment@gmail.com	All Inspections
Young, Rob		rob.young@state.co.us	COGCC EPS

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236712	WELL	PR	01/31/2002	OW	121-09205	KINCHELOE 1	SI

General Comment:

Spill Inspection

Around 1:15 pm on 12/22/2019 Inspector received call from a neighbor that there was a spill on the Kinchloe well location. Neighbor said that the well was shut in now. Inspector contacted operator and two vac trucks and a backhoe brought to location to contain oil and produced water. Apparently the treater dump valve got stuck and the 2-300 bbl oil tanks over ran filling the berm, the berm failed in two places and oil/produced water flowed down the access road to the well and off location into a winter wheat field. Inspector asked the vac truck drivers to get the free oil and the backhoe operator to berm the stained soil that was recovered. The landowner was made aware of the situation. Operator was asked to contact Washington County LGD and complete a Form 19I.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		
PW/CO	Tank	>= 5 bbls		
Comment: Treater dump valve failed causing 2-300 bbl tanks to overflow. Berms failed and oil and produced water flowed down access road to well and into crop field.				
Corrective Action: Report spill or release of E&P waste or produced fluids Remove free fluids and contact COGCC EPS staff per Rule 906.b. 24 hours to remove free fluids. Twenty-four hours for notification and 72 hours for Initial Form 19 Report.				Date: <u>12/25/2019</u>

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 236712 Type: WELL API Number: 121-09205 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: None Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: NO 2+ feet Freeboard: YES

Comment: dry, produced water is going to injection well

Corrective Action

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688306576	Investment Equipment Kincheloe 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020054