

TEP Rocky Mountain LLC
DOE /2-W-27
Location # 335233



The 4 -batteries not properly stored sitting at injection well have been removed from location.