

COGCC Follow Up Inspection Photos FIR DOC # 690101612 dated 12/20/2019
Location: KP Kauffman - Charter Schneider Tank Battery
Facility ID #444630
REM #9522



**View of excavation; flowlines exposed in ground and walls
(view west).**



Cut ends of flowlines exposed in excavation (view to NW).

COGCC Follow Up Inspection Photos FIR DOC # 690101612 dated 12/20/2019
Location: KP Kauffman - Charter Schneider Tank Battery
Facility ID #444630
REM #9522



Cut ends of flowlines exposed in excavation (in west wall).



Cut ends of flowlines exposed in excavation (in north wall).

COGCC Follow Up Inspection Photos FIR DOC # 690101612 dated 12/20/2019
Location: KP Kauffman - Charter Schneider Tank Battery
Facility ID #444630
REM #9522



Cut ends of flowlines exposed in excavation (in south wall).



Cut ends of flowlines exposed in trenching/ excavation recently completed approximately 30' north of the north wall of the primary excavation; ends open to atmosphere.