

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-08228
Date: 12-20-2019



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with perennial grasses such as smooth brome, crested wheatgrass, and sand dropseed.



Photo 3. View of area (approximately 15 to 20 feet wide and long) in the southwestern reclamation area where vegetation is not present and deep truck tracks marked in soil. Area needs reclamation.



Photo 4. Another view of area in the southwestern project area where there is bare soils and truck tracks in the interim reclamation area.



Photo 5. View of reference area vegetation comprised of mosaic of sagebrush shrubland and pinyon and juniper woodland.