


Standley\* Robert K DBA Otis Energy, Geoglein 5  
121-10574  
Inspection #688306571  
12/19/2019  
Engineering Inspection




Colorado Oil and Gas Conservation Commission  
40.1345, -102.81303, 4130.6ft, 140°  
12/19/2019 04:35:39 PM



A photograph of an oil pumpjack in a field. The pumpjack is a large metal structure with a long arm and a counterweight, used for extracting oil from the ground. It is situated in a flat, open field with a clear sky in the background. The pumpjack is connected to a wellhead and a series of pipes. The overall scene is industrial and rural.

Colorado Oil and Gas Conservation Commission  
40.1351, -102.80147, 4120.7ft, 42°  
12/19/2019 04:39:02 PM



Flowline GPS at  
wellhead.

Colorado Oil and Gas Conservation Commission  
40.13521, -102.80147, 4124.0ft, 249°  
12/19/2019 04:39:18 PM





Flowline GPS at  
treater.

Colorado Oil and Gas Conservation Commission  
40.09509, -102.79128, 10°  
12/19/2019 04:41:09 PM



Colorado Oil and Gas Conservation Commission  
40.13412, -102.80331, 4143.7ft, 295°  
12/19/2019 04:41:11 PM



Colorado Oil and Gas Conservation Commission  
40.13413, -102.80334, 4130.6ft, 352°  
12/19/2019 04:41:19 PM