

**FORM  
INSP**Rev  
X/15

# State of Colorado Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/13/2019

Submitted Date:

12/17/2019

Document Number:

693200472

**FIELD INSPECTION FORM**
 Loc ID 335165 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

4 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
Heil, John		john.heil@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275310	WELL	PR	11/14/2006	GW	045-13517	HOOKEK 30-02D	EG
280810	WELL	PR	11/14/2006	GW	045-11360	HOOKEK 30-02A	EG
280836	WELL	PR	11/14/2006	GW	045-11373	HOOKEK 30-01C	EG
468820	SPILL OR RELEASE	AC	10/23/2019		-	SPILL/RELEASE POINT	EG

**General Comment:**

COGCC joint inspection with EPS J. Heil and Western Integrity Inspector R. Murray

Engineering Integrity Inspection performed on December 13, 2019

Inspection performed with FLIR camera GF77

**Inspected Facilities**

Facility ID: <u>275310</u>	Type: <u>WELL</u>	API Number: <u>045-13517</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>280810</u>	Type: <u>WELL</u>	API Number: <u>045-11360</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>280836</u>	Type: <u>WELL</u>	API Number: <u>045-11373</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>468820</u>	Type: <u>SPILL OR</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EG</u>

**Optical Gas Imaging Survey**Survey Type: ComplaintCurrent Operations: ☒ Production ☐ Workover ☐ Flowback ☐ Referred to APCDGPS(entrance of location): Lat: 39.501030 Long: -107.813800Wind: Light Speed: 5 (mph) Direction From: west Weather: Cloudy Temperature: 40 (F)Assisting Staff: John Heil Camera #: \_\_\_\_\_☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM

Equipment
Separation Equipment
Water Tank(s)
Oil Tank(s)

Comment: 2 Leaks were detected at pressure switches in separators house,  
Leaks were detected in tank battery at pressure relief valve and thief hatches  
FLIR videos attached

Corrective Action: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 01/02/2020**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402265050	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015054">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015054</a>
693200473	tep2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015049">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015049</a>
693200474	tep3	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015050">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015050</a>
693200475	tep5	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015051">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015051</a>
693200476	tep1	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015052">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015052</a>
693200477	tep4	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015053">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015053</a>