

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/17/2019

Submitted Date:

12/17/2019

Document Number:

687905930

**FIELD INSPECTION FORM**

Loc ID 326569 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

- 25 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258102	WELL	PR	12/31/2001	GW	067-08324	MAGOON D 1	PR

**General Comment:**

[Site inspection and equipment inventory with photos at the end of this report. This inspection report has been created to update the equipment inventory and identify CA's.](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel access road through locked gate.		
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	Labels and placards posted on produced water tank, antifreeze and compressor oil storage tanks. Labels and placards missing/deteriorated on pumpjack engine oil tank.		
Corrective Action:	Update signs per Rule 210.	Date:	02/17/2020
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	Contact information posted on signs.		
Corrective Action:		Date:	
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused valve and spool piece laying along side of the pumpjack. Empty plastic lube oil tote sitting along cattle panels.		
Corrective Action:	Remove unused equipment per Rule 603.f.	Date:	01/01/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	SEPARATOR		
Comment:	Cattle panels around separator, compressor building, meter house, bulk storage tanks and solar array.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Cattle panels around PBV.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Vertical Heated Separator	# 1		corrective date

Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Prime Mover	# 1		
Comment:	Natural gas engine installed on pumping unit.		
Corrective Action:			Date:
Type: Flow Line	# 8		
Comment:	1-4" flowline from wellhead to separator. 1-1" flowline from separator to pumpjack engine fuel gas. 1-2" flowline from separator dump valve to produced water tank and also to offsite produced water gathering system. 1-4" flowline from separator to compressor. 1-4" flowline from compressor to meter house. 1-2" flowline from compressor scrubber dump valve to produced water gathering system. 1-4" compressor by-pass. 1-4" flowline from meter house to offsite dogleg.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:	Ajax compressor located in compressor building. Currently not in operation.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead with block valve assembly installed.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Solar array with storage batteries.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:	Static grounding reel installed on tank.				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO			
Comment:				
Corrective Action:				Date:

**Flaring:**

Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**

Facility ID: 258102 Type: WELL API Number: 067-08324 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

### Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
				Material Handling And Spill Prevention		Spill prevention on compressor coolant tank.
				Material Handling And Spill Prevention		Spill prevention for compressor oil tank.
				Material Handling And Spill Prevention		Spill prevention on pumpjack engine oil tank.
Gravel	Pass	Gravel	Pass			

Comment: Location covered in snow at time of inspection.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402267350	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017167">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017167</a>
687905931	Overview photo looking West.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017149">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017149</a>
687905932	Unused lube oil tote.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017150">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017150</a>
687905933	Missing/deteriorated labels on engine oil tank.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017151">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017151</a>
687905934	Unused equipment valve and spool piece.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017152">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017152</a>