

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/18/2019

Submitted Date:

12/18/2019

Document Number:

693502005**FIELD INSPECTION FORM**

Loc ID 320185 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num:

**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments6 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202944	WELL	PR	08/01/2019	OW	001-08349	GUTHRIE 1	PR

**General Comment:**

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Deep ruts in road. Proper BMP's not in place and road is not properly maintained.		
Corrective Action	Install or repair required BMPs per Rule 1002.f.(2)C	Date:	01/08/2020
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:	Piles of debris on location see pictures.		
Corrective Action:	Comply with rule 603f	Date:	12/25/2019
Type	UNUSED EQUIPMENT		
Comment:	Old well head and flowlines on location.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/08/2020
Type	WEEDS		
Comment:	Weeds on location around dead men and electric panel.		
Corrective Action:	Comply with rule 603 f	Date:	12/25/2019
Type	OTHER		
Comment:	Stained soil and grease around well head		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	01/08/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Square tubing		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type: Ancillary equipment	# 1		corrective date
Comment:	Electric panel		

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 1		
Comment:	Guy line anchor not properly marked		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 01/01/2020

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 202944 Type: WELL API Number: 001-08349 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday December 18, 2019 at approximately 9:56AM, I, Inspector Randy Silver, conducted an on-site inspection.</p> <p>Location: Guthrie #2</p> <p>Operator: KP Kauffman</p> <p>API#: 05-001-08349</p> <p>County: Adams</p> <p>While there, I observed producing well site.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Road access: Rule 1002 f (2) c Corrective action date of 1-8-20 See photo 2</p> <p>Weeds: Rule 603 f Corrective action date of 12-25-19 See photos 3,5,6,7,8</p> <p>Unused equipment: Rule 603 f Corrective action date 1-8-20 See photos 8,9</p> <p>Stained soil: Rule 907 e Corrective action date of 1-8-20 See photos 10</p> <p>Debris: Rule 603 f Corrective action date of 12-25-19 See photos 3,7</p> <p>Guyline Anchor: Rule 1003 a Corrective action date 1-1-20 See photo 6</p> <p>Weather conditions: Clear location dry</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	silverrr	12/18/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402267351	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017168">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017168</a>
693502006	Loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017154">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017154</a>