

Inspection Photos

Operator: Enduring Resources
Location/API #: 067-08501
Date: 12-23-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is mowed and appears to be progressing with grasses such as smooth brome and crested wheatgrass.



Photo 3. View of the northern project area from the northwestern corner facing eastward. What appears to be surface owner equipment and materials is stored in the northern project area.



Photo 4. Another view of surface owner equipment and materials stored within the northern project area.



Photo 5. View of reference area vegetation comprised of open grass field with both native and introduced grasses in dormant vegetative condition.