

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/27/2019

Submitted Date:

12/28/2019

Document Number:

696101722

**FIELD INSPECTION FORM**

Loc ID 331096 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 69175  
Name of Operator: PDC ENERGY INC  
Address: 1775 SHERMAN STREET - STE 3000  
City: DENVER State: CO Zip: 80203

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name       | Phone | Email                            | Comment                         |
|--------------------|-------|----------------------------------|---------------------------------|
| ,                  |       | cogccinspection@pdce.com         | <a href="#">All Inspections</a> |
| ,                  |       | dnr_cogccengineering@state.co.us |                                 |
| Schlagenhauf, Mark |       | mark.schlagenhauf@state.co.us    |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 258490      | WELL | PA     | 01/29/2019  | GW         | 123-20147 | NAT'L HOG FARM 14-9 | PA          |

**General Comment:**

This is a **PLUGGED & ABANDONED WELL / ABANDONED BATTERY** inspection.  
Well(s): 1: Plugged & Abandoned | PA.  
Battery: Abandoned. ALL equipment has been removed.  
Reclamation progressing.  
Abandoned Battery SE corner GPS coordinates: 40.407174, -104.450663  
Follow-up to Field Inspection Report doc. #696100758 dated 04/12/2019.

**Location**

|                    |             |       |  |
|--------------------|-------------|-------|--|
| <b>Lease Road:</b> |             |       |  |
|                    | Type Access |       |  |
| comment:           | Adequate    |       |  |
| Corrective ActionL |             | Date: |  |

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | UNUSED EQUIPMENT  |       |  |
| Comment:           | <p>Prior insp:<br/>                 Unused equipment (gas meter run &amp; riser) at Abandoned Battery site.<br/>                 Refer to Rule 603.f.<br/>                 Remove unused equipment (gas meter run &amp; riser) at Abandoned Battery site.<br/>                 Comply w/ Rule 603.f.<br/>                 Corrective Action date: Open</p> <p>This insp:<br/>                 * Unused equipment (gas meter run &amp; riser) at Abandoned Battery site. NOW removed.<br/>                 See photos #3, 4.</p> |       |  |
| Corrective Action: |   | Date: |  |

Overall Good:

| <b>Spills:</b> |      |        |  |
|----------------|------|--------|--|
| Type           | Area | Volume |  |
|                |      |        |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Venting:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Yes/No             |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 258490 Type: WELL API Number: 123-20147 Status: PA Insp. Status: PA

**Workover**

Comment: Plugged & Abandoned | PA.  
Well appears to be cut / capped.  
Form 6 doc. #401954234 indicates plugging date: 01/29/2019. Approved.  
Reclamation progressing.

Corrective Action:

Date:

**Completion**

Operation:

Date Flowback:

Contractor:

Comment:

Corrective Action:

Date:

| Reclamation - Storm Water - Pit  |                 |                         |                       |               |                          |             |
|--|-----------------|-------------------------|-----------------------|---------------|--------------------------|-------------|
| <b>Storm Water:</b>  |                 |                         |                       |               |                          |             |
| Loc Erosion BMPs   | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment     |
| Mulching   |                 | Gravel                  |                       |               |                          |             |
| Comment: <input style="width:90%;" type="text"/><br>Corrective Action: <input style="width:90%;" type="text"/> |                 |                         |                       |               |                          | Date: _____ |
| <b>Pits:</b> <input type="checkbox"/> NO SURFACE INDICATION OF PIT   |                 |                         |                       |               |                          |             |

| COGCC Comments   |        |            |
|--|--------|------------|
| Comment  | User   | Date       |
| <p><b>COGCC Inspection Report Summary:</b></p> <p>On FRI 12/27/2019 at approximately 14:58 hrs. I, Bret Evins, conducted an on-site inspection at:<br/>                     Operator Name: PDC ENERGY INC<br/>                     Location Name: NAT'L HOG FARM-65N63W /9SWSW<br/>                     Location ID: 331096<br/>                     Well Name: Nat'l Hog Farm 14-9<br/>                     API: 05-123-20147<br/>                     Location County: Weld County, Colorado<br/>                     Weather: Partly cloudy w/ partial snow coverage from prior storm.</p> <p>While there, I observed:<br/>                     Well(s): 1: Plugged &amp; Abandoned   PA.<br/>                     Battery: Abandoned. ALL equipment has been removed.<br/>                     Reclamation progressing.<br/>                     Abandoned Battery SE corner GPS coordinates: 40.407174, -104.450663</p> <p>Follow-up to Field Inspection Report doc. #696100758 dated 04/12/2019.<br/>                     During this inspection, the following prior possible compliance issues appear to be addressed:<br/>                     1.) Unused equipment (gas meter run &amp; riser) at Abandoned Battery site.<br/>                     Refer to Rule 603.f.<br/>                     Remove unused equipment (gas meter run &amp; riser) at Abandoned Battery site.<br/>                     Comply w/ Rule 603.f.<br/>                     Corrective Action date: Open<br/>                     * Unused equipment (gas meter run &amp; riser) at Abandoned Battery site. NOW removed.<br/>                     See photos #3, 4.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 12/28/2019 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 696101723    | Site photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5023438">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5023438</a> |