

**Inspection Photos**  
**Location Name:** NHF-65N63W /9NWSW  
**Location #:** 331573



**Photo #1**  
**NHF 13-9 (05-123-20921) Wellsite**  
**Temporarily Abandoned | TA**  
**Stained soil at wellhead perimeter**  
*prior insp.*



**Photo #2**  
**NHF 13-9 Wellsite**  
**Temporarily Abandoned | TA**  
*Stained soil at wellhead perimeter: Mitigated*

**Inspection Photos**  
**Location Name:** NHF-65N63W /9NWSW  
**Location #:** 331573



**Photo #3**  
**NHF 13-9, 24-9 Battery site**  
**Shut-down | Inactive**  
*prior insp.*



**Photo #4**  
**NHF 13-9, 24-9 Battery site**  
**Shut-down | Inactive**



**Inspection Photos**  
**Location Name:** NHF-65N63W /9NWSW  
**Location #:** 331573



**Photo #5**  
**NHF 13-9, 24-9 Battery site**  
**Unused Equipment**  
*Gas meter run, riser  
prior insp.*



**Photo #6**  
**NHF 13-9, 24-9 Battery site**  
**Unused Equipment**  
*Gas meter run, riser: **Company states plans to re-use***