

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/27/2019

Submitted Date:

12/28/2019

Document Number:

696101725

FIELD INSPECTION FORM

Loc ID 331575 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 69175
Name of Operator: PDC ENERGY INC
Address: 1775 SHERMAN STREET - STE 3000
City: DENVER State: CO Zip: 80203

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------------------|---------------------------------|
| , | | dnr_cogccengineering@state.co.us | |
| , | | cogccinspection@pdce.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 263571 | WELL | TA | 04/11/2019 | OW | 123-20923 | NHF 24-9 | TA |

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Shut-down | Inactive.

Centralized Battery serves 2 Location IDs (331573, 331575).
(Well(s): 2: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696101724 and/or Location ID #331573 for Battery / Facility, Equipment info.

| Location | | | |
|--|---|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action: | | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type | | | |
| Comment: | Refer to Field Inspection Report doc. #696101724 and/or Location ID #331573 for Battery / Facility, Equipment info. | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | | | |
| Corrective Action: | | | Date: _____ |
| Good Housekeeping: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Iron panel. | | |
| Corrective Action: | | | Date: |
| Type | | | |
| Comment: | Refer to Field Inspection Report doc. #696101724 and/or Location ID #331573 for Battery / Facility, Equipment info. | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Plunger Lift | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: | # | | |

| | | | |
|--|-----|-------|--|
| Comment: Refer to Field Inspection Report doc. #696101724 and/or Location ID #331573 for Battery / Facility, Equipment info. | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: Appears plumbed to surface. | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--|---|----------|---------------------|---------|-----------------------|
| | | | CENTRALIZED BATTERY | | 40.408457,-104.447118 |
| Comment: Centralized Battery serves 2 Location IDs (331573, 331575). Refer to Field Inspection Report doc. #696101724 and/or Location ID #331573 for Battery / Facility, Equipment info. | | | | | |
| Corrective Action: | | Date: | | | |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | Date: | | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 263571 Type: WELL API Number: 123-20923 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA.
All production valves shut.
Form 5A doc. #402004479 indicates DH plug set w/ pressure test. TA date: 02/15/2019.
(Approved).
PDC plans to return well to production later.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary:</p> <p>On FRI 12/27/2019 at approximately 16:20 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: PDC ENERGY INC Location Name: NHF-65N63W /9SESW Location ID: 331575 Well Name: NHF 24-9 API: 05-123-20923 Location County: Weld County, Colorado Weather: Partly cloudy w/ partial snow coverage from prior storm.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Shut-down Inactive.</p> <p>Centralized Battery serves 2 Location IDs (331573, 331575). (Well(s): 2: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696101724 and/or Location ID #331573 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p> | evinsb | 12/28/2019 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696101727 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5023442 |