

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/23/2019

Submitted Date:

12/23/2019

Document Number:

687905950

**FIELD INSPECTION FORM**

Loc ID 326068 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10000  
Name of Operator: BP AMERICA PRODUCTION COMPANY  
Address: 1199 MAIN AVENUE SUITE 101  
City: DURANGO State: CO Zip: 81301

**Findings:**

- 20 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">All Inspections</a>
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215813	WELL	PR	12/31/2001	GW	067-07418	GRACE COWEN A 1	PR

**General Comment:**

[Site inspection and equipment inventory with photos at the end of this report.](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Gravel access road through locked gate.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Sign posted at entrance to location.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information posted on sign.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused telemetry equipment, solar panel and J-box mounted on concrete pad not in use and disconnected sitting in southeast corner of location.		
Corrective Action:	Remove unused equipment per Rule 603.f.		Date: <u>01/23/2020</u>
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Cattle panels around wellhead and pumpjack.		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Cattle panels around separator.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Gas Meter Run	# 1		corrective date
Comment:	Located in separator building.		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:	All deadmen marked and noted from previous inspection.		

Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 4		
Comment:	1-4" steel flowline from wellhead to separator. 1-1" steel flowline from separator to pumpjack engine fuel gas. 1-2" steel flowline from separator dump valve to offsite produced water gathering system. 1-4" steel flowline from separator to sales line.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with block valve assembly installed.		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas engine on pumping unit.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 215813 Type: WELL API Number: 067-07418 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Pass	Spill prevention for engine oil tank.
Berms	Pass	Compaction	Pass			
Compaction	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			

Comment: [Stormwater BMP's appear to be functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402270732	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020642">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020642</a>
687905951	Overview photo looking North.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020635">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020635</a>
687905952	Unused equipment in Southeast corner.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020636">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020636</a>