

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2019

Submitted Date:

12/23/2019

Document Number:

688306585**FIELD INSPECTION FORM**Loc ID 317117 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 14855Name of Operator: CENTRAL OPERATING INCAddress: 1600 BROADWAY STE 1050City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Potter, Gail		centraloperatinginc@gmail.com	Office manager
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Whittington, Ellice		ellice.whittington@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Quintana, Laney	(303) 894-9576	centraloperatinginc@gmail.com	
Staley, Conner	3038949576	coidenverproduction@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236498	WELL	PR	07/03/1975	OW	121-08988	STATE 3	EG

General Comment:

COGCC Flowline Inspection/Reinspection. Photos Uploaded.

The Corrective Action identified during this COGCC (EG) field Inspection are located in the flowline section of report. ALL CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.

Corrective actions from previous inspection were completed (stuffing box leak and fix access road).

Inspected FacilitiesFacility ID: 236498 Type: WELL API Number: 121-08988 Status: PR Insp. Status: EG**Flowline**

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: This well is currently producing. The off location flowline (wellhead line) runs approximately 1880' north from the wellhead to the facility/battery. This off location flowline has not been registered with COGCC as operator has not submitted COGCC Form 44.
 Note: Operator has not registered any off location flowlines with COGCC. The Corrective Action outlined is applicable to all wells operated by Central Operating (including for this facility and the Marick, 121-08619). Additional inspections may be forthcoming.

Corrective Action: Operator shall comply with the following COGCC Rule: 1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off-location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.

Date: 10/31/2019**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402271017	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020992
688306596	Central Operating INC, State 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020985