

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/27/2019

Submitted Date:

12/27/2019

Document Number:

699300802**FIELD INSPECTION FORM**Loc ID 318561 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rwatzman@kpk.com	All Inspections
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241599	WELL	PR	03/01/2019	OW	123-09388	KIYOTA 2	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Transformers		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 241599 Type: WELL API Number: 123-09388 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 12/27/19 at approximately 1010 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location: Kiyoto 2 API # 05-123-09388 in Weld County Colorado.</p> <p>While there, I observed a producing wellsite this is a follow up inspection per Doc. # 699300025</p> <p>During this inspection the following compliance issues appear to have been addressed:</p> <p>907.e Housekeeping: Stained soil around 2" flow line riser appears to have been cleaned up and removed.</p> <p>605.d Mechanical Issue: 2" riser fittings appear to have been tightened.</p> <p>Reporting: Well report shows that it is a PR well, at time of inspection well appears to be PR.</p> <p>Weather is cold and overcast, location is frozen.</p> <p>No follow up on this site inspection needs to be conducted,</p> <p>Compliance issues appear to have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education Inspection.</p>	revasr	12/27/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300803	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5024543