

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/30/2019

Submitted Date:

12/30/2019

Document Number:

699500526**FIELD INSPECTION FORM**Loc ID 305939 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283948	WELL	TA	05/24/2016	GW	123-23718	GREEN XX 8-4	TA
440412	WELL	PR	04/01/2019	OW	123-40834	GREEN 2C-8HZ	PR
440413	WELL	PR	05/01/2019	OW	123-40835	GREEN 2N-8HZ	PR
440414	WELL	PR	04/01/2019	OW	123-40836	GREEN 4N-8HZ	PR
440415	WELL	PR	06/01/2019	OW	123-40837	GREEN 1N-8HZ	PR
440416	WELL	PR	03/01/2019	OW	123-40838	GREEN 3N-8HZ	PR
440417	WELL	PR	05/05/2016	OW	123-40839	GREEN 1C-8HZ	PR
440418	WELL	PR	05/03/2016	OW	123-40840	GREEN 5N-8HZ	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

1

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

1

Comment: Automation

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 283948 Type: WELL API Number: 123-23718 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____Facility ID: 440412 Type: WELL API Number: 123-40834 Status: PR Insp. Status: PRFacility ID: 440413 Type: WELL API Number: 123-40835 Status: PR Insp. Status: PRFacility ID: 440414 Type: WELL API Number: 123-40836 Status: PR Insp. Status: PRFacility ID: 440415 Type: WELL API Number: 123-40837 Status: PR Insp. Status: PRFacility ID: 440416 Type: WELL API Number: 123-40838 Status: PR Insp. Status: PRFacility ID: 440417 Type: WELL API Number: 123-40839 Status: PR Insp. Status: PRFacility ID: 440418 Type: WELL API Number: 123-40840 Status: PR Insp. Status: PR**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: TACorrective Action: Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of location may have been distorted due to weather conditions.	medinaj	12/30/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500527	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5024836