

Well Name: Ford Olson 2 API # 05-067-08789
IGE 128 API # 05-067-09568
IGE 129 API # 05-067-09908
IGE 130 API # 05-067-09909

Inspection Number: 687903685

Corrective Action: Leaking valves on production tanks

Correction Action Due: 2/1/2019

Action Completed: 2/1/2019

Action Taken: Replaced leaking valves on production tanks

Corrective Action: Oily rags on pumping unit

Correction Action Due: 2/11/2019

Action Completed: 2/4/2019

Action Taken: Pick up and clean oily rags and trash.

Corrective Action: Unused hose on Ford Olson 2 well head

Correction Action Due: 2/28/2019

Action Completed: 2/4/2019

Action Taken: Removed unused equipment from location

Corrective Action: Rubber tires in secondary containment, tear in secondary containment

Correction Action Due: 2/15/2019

Action Completed: 2/15/2019

Action Taken: Removed rubber tires from secondary containment, repaired tear in secondary containment.

