

Well Name: Olson Smith GU 2, IGE 127 **API #** 05-067-07911 05-067-09545
Inspection Number: 687903691
Corrective Action: Stuffing box leak
Correction Action Due: 2/1/2019
Action Completed: 2/1/2019
Action Taken: Repair stuffing box.

Corrective Action: Trash and rags on pumping unit skid
Correction Action Due: 2/11/2019
Action Completed: 2/4/2019
Action Taken: Clean up trash and rags.

Corrective Action: Pumping unit gearbox leak
Correction Action Due: 2/8/2019
Action Completed: 2/4/2019
Action Taken: Repaired pumping unit gearbox leak, clean up oil from leak.

Corrective Action: Thief hatch was found open.
Correction Action Due: 2/28/2019
Action Completed: 2/1/2019
Action Taken: Closed thief hatch.

Corrective Action: Tear in southern wall of secondary containment
Tires inside secondary containment
Correction Action Due: 2/28/2019
Action Completed: 2/4/2019
Action Taken: Repaired tear in secondary containment.
Removed tires from secondary containment.

