



Form Information

Form Name:	Compliance Follow Up Form
Submitter Name:	Luis Guerrero (l.guerrero@kosinm.com)
Submission Date:	Dec 23, 2019 10:08:28 PM MST
Server Receive Date:	Dec 23, 2019 10:08:33 PM MST
Reference Number:	20191224-18127558196
Location:	13 Road 51921, Bloomfield, NM 87413, USA Dec 23, 2019 10:02:49 PM MST [View Map]

Information

Name	l.guerrero@kosinm.com
Date	Dec 12, 2019
Well Name	MCMANUS GAS UNIT 33-22 2
API Number	50670894500
Select State	Colorado
Work type	COGCC Inspection AR
Action Complete	Compliance Inspection Actions Erosion Repairs

Photo of first corrective action completed



Completed work description Corrective Action 1

Repaired erosion channel.

Photo of second corrective action completed



Completed work description of corrective action 2

Installed silt trap.

Photo of third corrective action completed



Completed work description of corrective action 3
Photo of fourth corrective action completed



Completed work description of corrective action 4

Summary of all work completed

Cleaned up stained soils.

Replaced steel flex pipe and cleaned up stained soils.

Repaired erosion channel, installed silt trap, cleaned up stained soils, replaced steel flex pipe and picked up all trash and debris.