

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/06/2020

Submitted Date:

01/07/2020

Document Number:

689901629

FIELD INSPECTION FORM

Loc ID 307656 Inspector Name: COSTA, RYAN On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1801 BROADWAY SUITE 350
City: DENVER State: CO Zip: 80202

Findings:

- 7 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89174	WELL	SI	10/01/2019	GW	071-06753	GENGHIS 44-16	RI

General Comment:

This is a location and stormwater inspection.
ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.

Location

Lease Road:

Type	Access				
comment:					
Corrective Action					Date:

Overall Good:

Signs/Marker:

Type	WELLHEAD				
Comment:	Sign has been posted since previous inspection.				
Corrective Action:					Date:
Type	TANK LABELS/PLACARDS				
Comment:	Labeling/placards are not posted on the tank.				
Corrective Action:	Install sign to comply with Rule 210.d.				Date: 02/08/2020

Emergency Contact Number:

Comment:					
Corrective Action:					Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL				
Comment:	There are two pieces of unused pipe that need to be removed.				
Corrective Action:	Comply with Rule 603.f .				Date: 01/23/2020

Overall Good:

Spills:

Type	Area	Volume			
Produced Water	WELLHEAD	<= 1 bbl			
Comment:	There is a dripping water leak at the wellhead.				
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.				Date: 01/09/2020

In Containment: No

Comment:

Multiple Spills and Releases?

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1				
Comment:					
Corrective Action:					Date:

Paint

Condition					
Other (Content)					

Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	There is no secondary containment around the tank.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 906.d.(1).			Date: 01/31/2020

Venting:

Yes/No			
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: There is an erosion channel that has developed near the sediment trap at the south side of the location. The erosion channel is preventing stormwater from entering into the sediment trap.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 01/23/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689901630	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5030753