

Inspection Photos
Operator: BP America
Location/API #: 067-08494
Date: 1-6-2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation appears to be progressing with grasses such as intermediate wheatgrass and smooth brome.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of reference area, comprised of irrigated grass field largely with smooth brome.