

Inspection Photos
Location Name: Anderson 19-1-10
Location ID: 441824



Photo#1 LACT Unit/Gas Meter/(2) Electrical Boxes



Photo#2 (6)Production Tanks/(2) Produced water tanks/(2)VRTs

Inspection Photos
Location Name: Anderson 19-1-10
Location ID: 441824



Photo#3 (4) ECDs



Photo#4 Wellhead/Chem tank OPS 2501V Oil soluble Paraffin Solvent

Inspection Photos
Location Name: Anderson 19-1-10
Location ID: 441824



Photo#5 **Unused chemical tank**



Photo#6 **Automation RTU/(2)Separators**

Inspection Photos
Location Name: Anderson 19-1-10
Location ID: 441824



Photo#7 Buffer Tank/VRU



Photo#8 Bullplugs Missing

Inspection Photos
Location Name: Anderson 19-1-10
Location ID: 441824



Photo#9 Bullplugs Missing/Right bucket needs emptied out

Photo#10 VRT, Leaking from PRV

Inspection Photos
Location Name: Anderson 19-1-10
Location ID: 441824



Photo#11 VRT leaking from PRV



Photo#12 Balon valve leaking

Inspection Photos
Location Name: Anderson 19-1-10
Location ID: 441824



Photo#13 UNMARKED RISER

Photo#14 Full bucket sitting next to most north separator